











ARES 1 → 55 ↑ 91 ↘ 29					
x 2  (a)	x 6  (b)	x 6  (c)	x 16  (d)	x 4  (e)	
x 4  (f)	x 2  (g)	x 2  (j)	x 3  (m)	x 12 (3,5x30)  (n)	x 44 (3,5x16)  (o)
x 2 (ø6x18x2)  (p)	x 12 (6,3-16)  (r)	x 2 (M4-12)  (s)	x 2 (ø6)  (t)	x 30  (w)	x 1  (z)
x 2 (214 mm)  (h)		x 2 kpl.  (i)		x 4  (k)	
				x 1 (812 mm)  (l)	
 25 min					
					



1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW



5



6

