























OLJE 2D2S



A	C			D	E
1	1990	38	38	2	2½
2	1990	38	38	1	2½
3	1990	38	38	1	2½
4	1859	561	16	1	2½
5	1859	561	16	1	2½
6	910	610	16	1	2½
7	815	561	16	1	1½
8	815	561	16	1	1½
9	810			1	2½
10	1833	845	3	1	2½
11	814	46	16	2	1½
12	1374	402	16	2	1½
13	808	189	16	2	1½
14	400	120	16	2	1½
15	400	120	16	2	1½
16	757	120	16	2	2½
17	406	787	2,5	2	2½
-	Accessories			1	1½



1



2

4x $\phi 8 \times 30$ mm **f1**

2x $\phi 3,5 \times 13$ mm **p1**

2x **n1**










6x **b1**

12x 20/11 **r42**











8x $\phi 6 \times 13$ mm **e3**

2x 400 mm **w5\CR**

2x 400 mm **w5\CL**






3




4




1x  y1

8x  f9
φ6x30 mm





5




1x  y1





6



7



8



x2




14

x2

15

f1

f1 f1



x2

13

c415



j1

y1

y1

9

I



p10
p10

16

14

p10

p10

x2

15

II

x2

13

14

15

16



10



x2



8x  $\phi 5 \times 9$ mm **e19**


2x  400 mm **w5\DL**

2x  400 mm **w5\DR**



4x  $\phi 3,5 \times 16$ mm **p25**

2x  400 mm **t33**



8x  **l1**





x2 **IV**









A = B



V



11







12


2x
M4x20 mm
j1





2x
c415

6x
a1



13

2x  d5



14

