







17



A	C			D	E	A	C			D	E
1	1990	38	38	2	2½	11	804	46	16	1	1½
2	1990	38	38	1	2½	12	804	46	16	1	1½
3	1990	38	38	1	2½	13	798	189	16	2	1½
4	900	370	16	1	1½	14	300	120	16	2	2½
5	1859	321	16	1	2½	15	300	120	16	2	2½
6	1859	321	16	1	1½	16	748	120	16	2	1½
7	805	321	16	1	1½	17	306	778	2,5	2	1½
8	804	301	16	3	1½	18	1374	397	16	1	2½
9	805	64	16	1	1½	19	1374	397	16	1	2½
10	805	64	16	1	1½	20	1833	835	2,5	1	2½
						-	Accessories			1	1½

1



1x
25x25x16/2mm
n110








8x
φ6x30 mm
f9

5x
φ8x30 mm
f1


1x
GLUE
y1

4x
φ15x12mm
r1








1x
φ3,5x16 mm
p38



2



r1







3










8x
20/11
r42

4x
 $\phi 8 \times 30$ mm
f1

6x
b1



4



5





2x
300 mm
w37^{CR}

2x
300 mm
w37^{CL}







8x
 $\phi 6 \times 13$ mm
e3






5








6










7



8






9




10

I



II



!



11



x2



8x  $\phi 5 \times 9$ mm **e19**


2x  300 mm **w37^{DR}**

2x  300 mm **w37^{DL}**





4x  $\phi 3,5 \times 16$ mm **p25**

2x  **t25**

8x  **l1**





x2 **IV**




V

x2







12

8x  s67



13

12x  $\phi 5 \times 17 \text{ mm}$ d1







14



2x
M4x22 mm **j30**

2x
c415




6x
a1



a1




15




16

2x

 $\phi 3,5 \times 16$ mm **p38**

1x

 $\phi 5 \times 60$ mm **p17**

1x $86 \times 21 \times 15 / 1,5$ mm
 **n14**

1x
 **f35**
 $\phi 10 \times 50$ mm

